This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.



FIGURE 1 (PRIOR ART)






FIGURE 2B




Figure 3A




Figure 3B




FIGURE 4

<u>500</u> **START** 505 SET UP INTERRUPT HANDLER FOR TELEPHONE DIALOG 507 LAUNCH MAIN PROGRAM 510 GENERATE DISPLAY INFORMATION FOR MAIN SCREEN 515 DISPLAY INFORMATION ON MAIN SCREEN **520 CONTINUE MAIN PROGRAM OPERATION** 550 RECEIVE INTERRUPT FROM TELEPHONE MODULE 555 LAUNCH INTERRUPT HANDLER "TELEPHONE DIALOG" 560 DISPLAY 'TELEPHONE DIALOG" IN SEPARATE REGION 565 ANSWER NO - END PHONE DIALOG CALL? YES **570** ANSWER CALL **575** PROCESS CALL **580 UPDATE DISPLAY REGION** NO <u>585</u> END YES - END CALL; END PHONE DIALOG-CALL? Figure 5

Figure 6

And the second speed of the second se




Figure 7




Figure 8




Figure 9

The state of the s